FIRMWARE UPDATE RELEASE NOTE: ezPAC SA300

Version Identification:

V10.X7.XX Basic Fault + GOST13109-97 + Flicker IEC 61000-4-15 + Harmonics IEC 61000-4-7
V10.X6.XX Basic Fault + IEEE 1159 + Fast AI
V10.X5.XX Basic Fault + EN50160 + Flicker IEC 61000-4-15 + Harmonics IEC 61000-4-7
V10.X4.XX Basic Fault + IEEE 1159 + Flicker IEC 61000-4-15
V10.X3.XX Basic Fault + IEEE 1159 - obsolete (not used more with PC0138 REV.B)
V10.1X.XX +IEC 61850 server option

Date: 9/12/2009

Versions:
V10.15.13
V10.15.13
V10.4.13
V10.5.13
V10.6.13
V10.7.13

New Features:

1. Prepared for dual 20MHz/25MHz master clock operation.
2. IEC61850 - added GOOSE publisher and subscriber.
3. IEC61850 - added saving user-created datasets.

Bugs Fixed:

Problem: Some fault triggers could not be correctly traced if a fault setpoint returned to operation while a delayed release.