



FIRMWARE UPDATE RELEASE NOTE: **BFM136**

Date: 11/08/2011

Version: V18.4.2

MAIN: **BFM_18.4.2_3070.hex**

Every BFM136 must be updated to this FW version while using ENFORA GPRS modem and/or linked to expertpower Pro

New Features: Corrected GPRS modem initialization and XPW timing

1. Added configurable XPW connection idle timeout.
2. XPW reconnect time is lowered to 1 min.
3. GPRS idle timeout is increased to 1 min.
4. Corrected GPRS modem initialization to compensate delayed modem responses.
5. The default baud rate for Virtual RF modems is set to 57600 bps. Fix: Data update could happen between readings of the low and high words of the 32-bit Modbus register.