



FIRMWARE UPDATE RELEASE NOTE: **PM175** **PM175 Rus**

Version Identification: 500kHz AI SPI clock, corrected GPRS modem initialization and XPW timing

PM175	V25.2.9
PM175_Rus	V25.10.9

Date: 11/08/2011

Version: V25.2.9
V25.10.9

MAIN: **PM175_25.2.9_3BED.hex**
PM175_25.10.9_F99D.hex

Every PM175 must be updated to this FW version while using ENFORA GPRS modem and/or linked to expertpower Pro

New Features:

1. Added configurable XPW connection idle timeout.
2. XPW reconnect time is lowered to 1 min.
3. GPRS idle timeout is increased to 1 min.
4. Corrected GPRS modem initialization to compensate delayed modem responses.
5. AI SPI clock is reduced to 500kHz.

Bug Fixed:

Data update could happen between readings of the low and high words of the 32-bit Modbus register.